

TMS370 v1.4 ERRATA SHEET

- WPO voltage error fixed
- Reset feature improved
- Handshaking error fixed

Follow next steps to fix errors:

1. "START" -> "Control panel" -> "Add/Remove programs"
2. Remove previous version of tms370 control software
3. Install new version 1.4 tms370.exe
4. Un-mount (open/ remove) update jumper to enter update mode *
5. Power ON tms370 programmer board
6. "START" -> "update370.exe"
7. Select comm1 or comm2 serial port and start the update program
8. Power OFF tms370 programmer board
9. Mount (short/ insert) update jumper to leave update mode *
10. Start the tms370.exe control software**

***NOTE:** See TMS user's manual for more information

****NOTE** Click menu item "Help" -> "About" -> "Version"

Make sure, that TMS370 control software 1.4 (beta) displayed