

TMS370 v1.5 ERRATA SHEET

- Serial Ports comm1-comm8 available
- CP2101 USB drivers compatible (Comm -> USB converters, Virtual Com Port Drivers)

Requirements:

Win2000/XP/Win2003 OS only *

Follow next steps to fix errors:

1. "START" -> "Control panel" -> "Add/Remove programs"
2. Remove previous version of tms370 control software
3. Install new version 1.5 tms370.exe
4. Un-mount (open/ remove) update jumper to enter update mode **
5. Power ON tms370 programmer board
6. "START" -> "update370.exe"
7. Select comm1 or comm2 serial port and start the update program
8. Power OFF tms370 programmer board
9. Mount (short/ insert) update jumper to leave update mode **
10. Start the tms370.exe control software***

***NOTE: Version 1.5. not compatible with Win95/98 OS**

****NOTE See TMS370 User's Manual for details**

*****NOTE Click menu item "Help" -> "About" -> "Version"**

Make sure, that TMS370 control software 1.5 displayed